



Tim's Cartridge Error



SOB Cartridge in a CoCo



SOB Cartridge in a Multi-Pak

The shell should have been a quarter inch longer. This causes the cart to be a little more “wiggley” than it should have been.